STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 R-C FCL011193 B. WING 02/11/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 101 COUNTRY TIME LANE **EVERGREEN LIVING HOME #1** LEICESTER, NC 28748 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X4) ID (MS) COMPLETE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) DATE TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) (C 000) Initial Comments {C 000} Report by Glenn Hoppin A Complaint Follow-up Survey was conducted on February 11, 2015 starting at 9:00AM and ending at 9:45AM. Not all of the previously cited CONSTRUCTION SECTION deficiencies were corrected. Therefore, further action is required. MAR 3 0 2015 The remaining deficiencies that were observed RECEIVED are as follows: C 161 Housekeeping-Land Line Phone C 161 SECTION .0300 - THE BUILDING 10A NCAC 13G .0315 HOUSEKEEPING AND FURNISHINGS (a) Each family care home shall: (12) have at least one telephone that does not depend on electricity or cellular service to operate. (e) This Rule shall apply to new and existing. homes. This Rule is not met as evidenced by: 1.) At the time of survey it was observed that provided landline phone 3/2/6 there is no landline phone in the facility. Install a landline phone in the facility that does not depend on electrical or cellular service to operate. (C 170): Fire Safety-Any Other City Ordinances (C 170) SECTION .0300 - THE BUILDING 10A NCAC 13G .0316 FIRE SAFETY AND DISASTER PLAN (c) Any fire safety requirements required by city. ordinances or county building inspectors shall be Division of Health Service Regulation LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

Division of Health Service Regulation

0066

63CJ22

Administrator 3/27/15

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 R-C B. WING FCL011193 02/11/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 101 COUNTRY TIME LANE EVERGREEN LIVING HOME #1 LEICESTER, NC 28748 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION PRÉFIX EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLETE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) (C 170) Continued From page 1 (C 170) This Rule is not met as evidenced by: A joint fire drill was conducted with the Buncombe County Fire Marshals office, DSS, and the DHSR Construction Section. The live drill was conducted by the staff and 911 was called as part of the drill. The following conditions were observed 1.) During the drill the 911 dispatcher was unable to understand the staff member calling, because the staff member speaks only Korean. When the power was turned of to the facility the smoke detectors, the phones, and the wander alarm did not function. Based on these facts the Buncombe County fire Marshall is requiring an addressable monitored fire alarm system that will tell emergency responders what the emergency is and where to Commercial Fire alam
Company will submit the
plan to the fire marshall
will be installed. respond. Obtain bids for a monitored addressable fire alarm system and provide the Buncombe County Fire Marshals office and the DHSR Construction section with a set of installation drawings for approval before installing the system. Provide the DHSR Construction section with copies of all permits, plans, invoices, and any other supporting documentation when the system is complete. Contact the Fire Marshals office and the DHSR Construction section for final approval after installation.